

# Safety Alert

**Number: 16-05**

**Published: 23/02/2016**

**Subject: Confined Space Entry & Isolation Procedures**

## What Happened / Narrative

During a Confined Space Entry Audit it was discovered that isolations were not in compliance with control of work procedures.

## Why Did it Happen / Cause

No lock-out / tag-out system was in use as required by the isolation procedure.

Isolations were not checked by the people entering the space to confirm they were in place.

A Confined Space Rescue Plan was not completed to cover the work, and was not discussed during the TBT.

## Corrective Actions Taken / Recommendations


Discipline around compliance with procedures needs to be rigorous and tested to ensure the barriers are effective.

Anyone entering a confined space should verify that all isolations and any secondary LO/TO are in place, by physically checking for themselves.

PTW should not be issued until the issuing authority has a copy of the completed Rescue Plan (which needs to be understood by all involved) and has tested that isolations are in place and effective.

Lock-out/tag-out must be rigidly enforced during confined space entry to ensure equipment is not re-instated or operated inadvertently.

## Photographs / Supporting Information



*The information contained within this Safety Alert and the associated MSF web site is provided in good faith for the benefit of our members and does not necessarily constitute MSF guidance, nor represent the official view of the MSF or its members. The text as provided by submitting organisations may be amended to ensure that it is brief, informative and readable but will as far as reasonably practicable remain as per the intent of the original submission. For the avoidance of doubt no legal liability shall be attached to any guidance, recommendation, advice and/or statement contained therein. Contents should be reviewed individually by recipients who will determine relevance to their own operations.*